

July 18, 2007

From: MPC Computers

Due to our administrative oversight, we had not completed the Energy Star 3.0 registration process for the TransPort T3200 as of the date we shipped certain of these laptop units. We shipped 108 units of the TransPort T3200 to the State of Idaho between June 2006 and July 2007. This issue with Energy Star registration is relevant only to the TransPort T3200 and not to any other MPC computer products.

Please be assured that the TransPort T3200 is, and always has been, 100% compliant with the applicable and effective Energy Star specification standards at time of purchase. The oversight relates only to the registration process with Energy Star for the TransPort T3200, which registration process we completed successfully on July 12, 2007.

Please be assured also that the company has taken the necessary steps to avoid repeating the error. Specifically, MPC has added an individual from our Contract Compliance Team to our Product Review Board. This individual is responsible for ensuring that all industry standard testing has been completed and the proper paperwork has been submitted for the appropriate certifications. No product will be added to any Government contract without the notification from the Contract Compliance Team that all certifications have been received from the respective entities. These certification include, but are not limited to, WHQL, UL, FCC and Energy Star.

Our technical team is available to answer any questions.

Respectfully,

Renee Andrako
Contract Specialist
MPC-G, LLC
208-893-3616
raandrako@mpccorp.com